

Cause of Failure – 250 HP WEG Motor

Prepared for _____

Dreisilker Electric Motors, Inc.

352 Roosevelt Road

Glen Ellyn, IL 60137

Motor Nameplate Information

Make: WEG

Model: 25018ET3GKD447-

Serial No.: 28JUNE2016 1032

Motor Type: -

Phys Type: T.E.F.C.

Mounting: BASE-SOLID

Frame Size: 447/9T

Power Value: 250

Power Rating: HP

Voltage: 460

AMPS: 292

RPM: 1785

AC/DC/Other: AC

Hertz: 60

Phase: 3

Serv. Factor: 1.15

Insul. Class: F

Ambient: 40C

Code:

Design: --

Motor Findings

- Motor had contamination on the cooling fins
- Mechanical dimensions of bearing and shaft fits were in tolerance
- Motor failed Megger/Insulation Test, DC HiPot, and Surge Test
- Winding ties were broken
- White bubbling of insulation material was coming out of slot ends
- Winding shorted to ground at edge of laminations on one coil

Incoming Picture




Incoming Picture



No contamination on inside, but winding ties broken



Winding ties broken



Winding ties broken and white bubbling of insulation material out of slots




White bubbling of insulation materials and ties broken away



Coil that shorted to ground at edge of laminations



Coils bend at an angle coming out of lamination steel slots



Cause/Causes of Failure

- One motor coil shorted to ground where it came out of the slot at an angle
- The winding overheated causing ties to break and white bubbling of insulation material to come out of slot
- It is unknown if coil shorted to ground first or if winding overheated first

Methods for Prevention of Failure

- Manufactured and rewound motors coils should come straight out of the laminations slots before bending. Bending a coil on the edge of the slot will cause abrasion of insulating materials.
- Check the motor controls to make sure it did not cause an overloaded condition causing winding to overheat (however, no other evidence in other parts of this motor indicated an overload)